

SITE REQUIRES PPE AND IS TOBACCO FREE

REQUIRED PPE

Hard Hat

Protective Eye Wear

ANSI Z87 Certified

Class II High Vis Top with Sleeves

(vest, shirt, sweatshirt or jacket)

Work Shirt

(No tank tops or half shirts)

Footwear Requirements

- Sturdy
- 6" Lace up Boot
- Over Ankle
- Good Working Condition

CONDITIONAL PPE

Based on Customer, Project, or job specific requirements.

Hearing Protection

Recommended and available at all locations.

Face Shield Protection

Required whenever liquid corrosive materials are being handled.

Protective Gloves Required

When handling corrosives to protect against cement burns and rash.

High Vis Pants

May be required for night time projects.



TOBACCO FREE ZONE
Buildings & Vehicles